

# Oil Field Environmental Incident Summary

**Incident:** 20150416163705      **Date/Time of Notice:** 04/16/2015 16:37

**Responsible Party:** XTO ENERGY INC.

**Well Operator:** XTO ENERGY INC.

**Well Name:** INGA FEDERAL 41X-29

**Field Name:** HAYSTACK BUTTE

**Well File #:** 19907

**Date Incident:** 4/15/2015      **Time Incident:** 16:00

**Facility ID Number:**

**County:** DUNN

**Twp:** 148

**Rng:** 97

**Sec:** 29

**Qtr:**

**Location Description:** Within lined metal berm near tank battery

**Submitted By:** Jeremy Waldschmidt

**Received By:**

**Contact Person:** Cody Knetzger  
10481 1A ST SW  
Killdeer, ND 58640

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

|     | Spilled | Units   | Recovered | Units   | Followup | Units |
|-----|---------|---------|-----------|---------|----------|-------|
| Oil | 1       | Barrels | 1         | Barrels |          |       |

Brine

Other

**Description of Other Released Contaminant:**

N/A

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

none.

**Areal Extent:**

Spill was contained in a metal lined berm.

**Potential Environmental Impacts:**

None - Spill was contained in a line metal berm.

**Action Taken or Planned:**

Oil was recovered with a vacuum truck and placed back into production tank.

**Wastes Disposal Location:** Back into the production tank.

**Agencies Involved:**

**Updates**

---

**Date:** 4/17/2015    **Status:** Reviewed - Assigned to Other Agency

**Author:** Espe, Brady

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release, due to valve/piping connection leak, remained on location within the diking according to the report. NDIC retains oversight.